

**Georgia Department of Public Health
PUBLIC SWIMMING POOL INSPECTION RECORD**

Name of Facility COURTYARD BY MARRIOTT SPA		Address 3501 COURTYARD WAY	City COLUMBUS	County
Certified Pool Operator		Address ONE MARRIOTT DR	City WASHINGTON	County
Deficiencies found on the inspection are marked with a (X). A check mark (✓) indicates satisfactory compliance, and (N/A) means non-applicable. *Indicates a substantial health hazard. Other items may be considered substantial health hazards depending on severity. The pool must be closed until substantial health hazards are corrected. One or more substantial health hazards violated, two or more other items violated or repeated violations will result in an unsatisfactory rating. An unsatisfactory rating may result in enforcement action.				
POOL WATER	1. Water supply approved, adequate	X/✓	Notes	
	2. Depth properly marked	✓		
	3. Overflow facilities adequate	✓		
	4. Constant water level	✓		
	5. Turnover adequate	✓	(see addendum)	
	6. Disinfectant residual concentration 3.5	✓	(see addendum)	
	7. pH (7.2-7.8)	X	(see addendum)	
	8. Total Alkalinity	✓	(see addendum)	
	9. Calcium Hardness	✓	(see addendum)	
	10. Cyanuric Acid	✓	(see addendum)	
	11. Clarity	✓		
PUMPING FILTRATION AND TREATMENT SYSTEM	12. Pump operating properly	✓		
	13. Filters functioning properly	✓		
	14. Hair & lint strainers functioning properly	✓		
	15. Skimmers/Gutters maintained & operating properly	✓		
	16. Chemical feeders operating properly	✓		
	17. Recirculation and filtration equipment readily accessible	✓		
DECK AND POOL AREA	18. Pool & Decks clean and in good repair	✓		
	19. Night lighting adequate	✓		
WATER AND FACILITIES	20. Hot & cold water under pressure	✓	(see addendum)	
	21. Adequate toilet facilities & showers	✓	(see addendum)	
SEWAGE DISPOSAL	22. Sewage disposal method: Public	✓		
SAFETY PRE-CAUTIONS	23. Life line in place/Separation of wading pool	✓	(see addendum)	
	24. Warning/Safety sign posted in clearview of pool area	✓		
	25. First aid kits available & properly equipped	✓	(see addendum)	
	26. Emergency & lifesaving equipment in conspicuous place	✓		
	27. Emergency phone provided and hard wired	✓	(see addendum)	
	28. Gas cylinder precautions adequate	✓	(see addendum)	
	29. Proper barrier around pool	✓		
OPERATOR AND RECORDS	30. Main drains properly covered and maintained	✓		
	31. Certified Pool Operator		(see addendum)	
	32. Lifeguard(s) (if provided) has proper certification	✓	(see addendum)	
	33. Trained operator on duty	✓		
	34. Appropriate records on file	✓		
	35. Pool test kit(s) available and adequate for all necessary tests	✓	(see addendum)	
36. Other	✓	(see addendum)		
Remarks				
Date of Inspection 02/15/2012	Discussed with (Signature & Title)		Inspected by (Signature & Title) Environmental Health Specialist I	

SATISFACTORY

UNSATISFACTORY

ENFORCEMENT

None

Permit Suspended

Closed Voluntarily

Re-inspection needed within days

Hearing Requested/Recommended

Permit No. 106-P29

Expiration Date

2013	12	31
YY MM DD		

Purpose:

1

1. Routine
2. Follow-up
3. Request
4. Complaint
5.

Other _____

Length of Inspection 732 Minutes

Pool Type:

Swimming/Pool

Spa

Special Purpose

Pool: Activity/Interactive/Wading
Type: Pool

Required Turnover Rate 33.00 hours
Type of Disinfectant _____

Required Concentration _____

Bather Load

			8
--	--	--	---

Laboratory Sample

1

1. None
2. Water
3. Other

Reason for Sample: _____

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD ADDENDUM

Name of Facility		Address	City	County
COURTYARD BY MARRIOTT SPA		3501 COURTYARD WAY	COLUMBUS	
Operator		Address	City	County
		ONE MARRIOTT DR	WASHINGTON	
Item Number	Notes			
5	100 GPM			
6	3.5			
7	<7.0			
8	did not check due to PH			
9	NA			
10	NA			
20	in adjacent hotel rooms			
21	adjacent hotel rooms and lobby			
23	NA-3 ft and less			
25	located at front desk			
27	dial 911			
28	NA			
31	Chris Smith			
32	NA			
35	in pump room			
36	water fountain and clock			